











XNT Soldering Tips


Chisel






A = Width mm
B = Thickness mm
C = Length mm






Model	A	B	C	PU	Order No.
XNT 1SC 	0.4	0.15	27	1 10	T005 44 862 99 T005 44 862 10
XNT 1SCNW 	0.3	0.1	27	1 10	T005 44 881 99 T005 44 881 10
XNT 4X 45° 	1.2	0.4	34.6	1 10	T005 44 874 99 T005 44 874 10
XNT 6 	1.6	0.4	29.5	1 10	T005 44 856 99 T005 44 856 10
XNT A 	1.6	0.4	28	1 10	T005 44 851 99 T005 44 851 10
XNT AX 	1.6	0.8	28	1 10	T005 44 864 99 T005 44 864 10
XNT B 	2.4	0.8	27	1 10	T005 44 857 99 T005 44 857 10
XNT BX 	2.4	0.8	36.5	1 10	T005 44 882 99 T005 44 882 10

Round



A = Width mm
B = Thickness mm
C = Length mm

Model	A	B	C	PU	Order No.
XNT 1LX 	0.2		42.8	1 10	T005 44 872 99 T005 44 872 10
XNT 1S 	0.2		28.5	1 10	T005 44 852 99 T005 44 852 10
XNT 1SLX 45° 	0.4		39.5	1 10	T005 44 875 99 T005 44 875 10




Model	A	B	C	PU	Order No.
XNT C 	3.2	0.8	27	1 10	T005 44 858 99 T005 44 858 10
XNT D 	4	0.8	28	1 10	T005 44 853 99 T005 44 853 10
XNT H 	0.8	0.4	28	1	T005 44 859 99
XNT HX 30° 	0.8	0.4	36.5	1 10	T005 44 873 99 T005 44 873 10
XNT K 	1.2	0.4	28	1 10	T005 44 860 99 T005 44 860 10
XNT MX	3.2	0.8	37.5	1 10	T005 44 883 99 T005 44 883 10
XNT L SOLDERING TIP 20MM	3.2	0.8	37.5	1 1	T005 44 866 99 T005 44 866 10
XNT L SOLDERING TIP 20MM	3.2	0.8	37.5	1 1	T005 44 867 99 T005 44 867 10





Sloped



A = Width mm
B = Thickness mm
C = Length mm


Model	A	B	C	PU	Order No.
XNT 4 	1.2		29.5	1	T005 44 855 99
				10	T005 44 855 10
XNT AA 45° 	1.6		28	1	T005 44 884 99
				10	T005 44 884 10
XNT BB 45° 	2.4		28	1	T005 44 885 99
				10	T005 44 885 10


Model	A	B	C	PU	Order No.
XNT CC 45° 	3.2		28	1	T005 44 886 99
				10	T005 44 886 10
XNT F 45° 	1.2		28	1	T005 44 887 99
				10	T005 44 887 10

Conical




A = Width mm
B = Thickness mm
C = Length mm


Model	A	B	C	PU	Order No.
XNT 1 	0.5		27	1	T005 44 850 99
				10	T005 44 850 10


Model	A	B	C	PU	Order No.
XNT S 	0.4		37.5	1	T005 44 868 99
				10	T005 44 868 10
XNT 1L SOLDERING TIP 02MM					T005 44 871 10 USOLD_ T005 44 871 99

Gull Wing




A = Width mm
B = Thickness mm
C = Length mm


Model	A	B	C	PU	Order No.
XNT GW1 			33	1	T005 44 854 99
				10	T005 44 854 10

Model	A	B	C	PU	Order No.
XNT GW2 KURZ 			27.5	1	T005 44 880 99
				10	T005 44 880 10

Knife



A = Width mm
B = Thickness mm
C = Length mm

Model	A	B	C	PU	Order No.
XNT KN 	2.0	4	33	1	T005 44 863 99
				10	T005 44 863 10



SMT

A = Width mm
 B = Thickness mm
 C = Length mm


Model	A	B	C	PU	Order No.
XNT SMT 01	10.4	0.6	7.1	1	T005 44 876 99
XNT SMT 02	16.8	0.6	7.1	1	T005 44 877 99

Model	A	B	C	PU	Order No.
XNT SMT 03	20.8	0.6	7.1	1	T005 44 878 99

Measuring tip

A = Width mm
 B = Thickness mm
 C = Length mm

Model	A	B	C	PU	Order No.
XNT Measuring tip			31.3	1	T005 44 861 99



Einschraubspitze

A = Width mm
 B = Thickness mm
 C = Length mm

Model	A	B	C	PU	Order No.
XNT Einschraubspitze M4	M4		26	1	T005 44 879 99



Soldering iron and safety rest

Soldering tips and nozzles

Preheating plates

Soldering bathes

Circuit board holder

Solder feeder

Hot air heating gun

Temperature measuring

Accessories